













































INSTRUMENTO	RESOLUÇÃO MEDIDA	INSTRUMENTO	RESOLUÇÃO MEDIDA
 0 10 20 30 40 0 5 10		 0 1 2 0 4 8	
 0 2 0 4 8		 0 10 20 30 40 0 5 10	
 0 1 2 0 4 8		 0 1 2 3 4 5 6 7 8 9 0 0 1 2 3 4 5 6 7 8 9 0	
 0 5 10		 0 4 8	
 0 1 2 0 4 8		 0 20 30 40 50 0 1 2 3 4 5 6 7 8 9 0	
 0 10 20 30 40 50 0 1 2 3 4 5 6 7 8 9 0		 0 5 10	
 0 1 2 0 1 2 3 4 5 6 7 8 9 0		 0 1 2 0 4 8	
 0 1 2 0 4 8		 0 10 20 30 40 0 5 10	
 0 5 10 0 1 2		 0 4 8	
 0 4 8		 0 10 20 30 40 0 5 10	



Paquímetro em polegada decimal – Converta para polegada fracionária

